






HYP 100 Suregrip HYP Plasma Cutting Torch Range

Rating: 100A Air gas, @ 60% duty cycle.
Air-Cooled Cutting Torch Range



Contact Cutting

- | | | | | |
|---|---|---|---|---|
|  |  |  |  |  |
| P220051
Swirl Ring
Maximum Life,
100A | P220037
Electrode
100A | Refer to Cutting
Tip Table | Refer to
Retaining
Cap Table | P220065
Hand Shield,
Hand, 100A |

Model

Description	Part No.	
	HYP Plasma Cutting Torch Package	4mt HYP100-40-CC1

Alternative torch packages can be configured using the configurator on page 12

Wear Parts

Cutting Tips

Part No.	Description	Bore Ø A
P220011	Tip 100A Shield	1.5mm

Retaining Caps

Part No.	Description
*HYP1230	Retaining Cap, 100A

Spare Parts

Part No.	Description
1	HYP1201 ST-120 Torch Head Kit
2	HYP2514 Plasma Handle Kit
3	SCPSP1 Screw Pack
4	SCP2516 Plasma Safety Trigger
5	SCP8015 Location Block
6	*SCP8019-40-# Cable Assembly Complete x 4mt
	*SCP8019-60-# Cable Assembly Complete x 6mt

*Denotes torch package standard wear part set-up
For more information please refer to the following sections:
•Cable Terminations Page 10
•Master Wear Parts Table Page 19-21
•Wear Parts Configuration Tables Page 22-23