







HYP 100R Suregrip HYP Plasma Cutting Torch Range

Rating: 100A Air gas, @ 60% duty cycle.
Air-Cooled Cutting Torch Range



Contact Cutting

- | | | | | |
|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-----------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|  |  |  |  |  |
| P220051
Swirl Ring
Maximum Life,
100A | P220037
Electrode
100A | Refer to Cutting
Tip Table | Refer to
Retaining
Cap Table | P220065
Hand Shield,
Hand,100A |

Model

Description	Part No.	
	HYP Plasma Cutting Torch Package	4mt HYP100R-40-CF4

Alternative torch packages can be configured using the configurator on page 12

Wear Parts

Cutting Tips

Part No.	Description	Bore \varnothing A
P220011	Tip 100A Shield	1.5mm

Retaining Caps

Part No.	Description
* HYP1230	Retaining Cap, 100A

Spare Parts

Part No.	Description
1	HYP1201 ST-120 Torch Head Kit
2	HYP2514C Plasma Handle Kit
3	SCPSP1 Screw Pack
4	SCP2516 Plasma Safety Trigger
5	SCP8015 Location Block
6	* SCP8019C-40 -# Cable Assembly Complete x 4mt
	* SCP8019C-60 -# Cable Assembly Complete x 6mt

*Denotes torch package standard wear part set-up
For more information please refer to the following sections:
 • Cable Terminations Page 10
 • Master Wear Parts Table Page 19-21
 • Wear Parts Configuration Tables Page 22-23