


SCB 50 Suregrip CBR Plasma Cutting Torch Range

Rating: 50A Air/N₂ gas, @ 60% duty cycle.

Air-Cooled Cutting Torch Range



Model

Description	Part No.	
	4mt	6mt
Suregrip CBR Plasma Cutting Torch Package	SCB50-40-CF6	SCB50-60-CF6

Alternative torch packages can be configured using the configurator on page 10

Wear Parts

Cutting Tips


Part No.	Description	Bore \varnothing A	Amps
P1304	Cutting Tip	1.0mm	50A
P1306	Cutting Tip Extended Contact	1.0mm	50A
P1304F-10	Cutting Tip Flat	1.0mm	50A
*P1305	Cutting Tip Conical	1.0mm	50A
P1370	Cutting Tip Extended	1.0mm	50A
P1395	Cutting Tip Extended Long Life	1.0mm	50A
P1395-11	Cutting Tip Extended Long Life	1.1mm	60A
P1396	Cutting Tip Long Life	1.0mm	50A
P1396-11	Cutting Tip Long Life	1.1mm	60A

Retaining Caps

Part No.	Description
*P5.710.121	Retaining Cap

Spare Parts

Part No.	Description
1	SCP5008 O Ring
2	SCB1352 SCB50 70° Torch Head Kit
3	SCP5014/HF Plasma Handle Kit
4	SCPSP1 Screw Pack
5	SCP2516 Plasma Safety Trigger
6	*SCP5019-40-# Cable Assembly Complete x 4mt
	*SCP5019-60-# Cable Assembly Complete x 6mt
7	P166 Circle Cutting Attachment Kit



*Denotes torch package standard wear part set-up
 For more information please refer to the following sections:
 • Cable Terminations Page 9
 • Master Wear Parts Table Page 18-26
 • Wear Parts Configuration Tables Page 27-28